

## TOSB BIAS OTOMOTIV TEST MERKEZI

2. Cadde, 2485. Sok. No:2/2, 41420 TOSB Otomotiv OSB/Çayırova/Kocaeli

Tel: (+90262) 502 21 41 info@bias.com.tr https://biastest.com.tr/

## **TEST REPORT**



Datakom Elektronik Mühendislik San. Ve Tic. A.S.

**Customer Name/ Address** 

Şerifali Mahallesi, Bayraktar Bulvarı, Kutup Sokak No:26, 34775

Ümraniye/İSTANBUL

**Order No** 

: TEST221118ESi01

Name and Identity of Test Item

Voltage Indicator

The Date of Receipt of Test item

10.02.2023

**Date of Test** 

13.02.2023

Number of Pages of The Report

BİAS Mühendislik Ltd. Şti. Gebze Branch Office accredited by TÜRKAK under registration number AB-1478-T for TS EN ISO/IEC 17025:2017 as test laboratory" TS EN ISO/IEC 17025:2017.

Turkish Accreditation Agency (TURKAK) is a signatory to the European co-operation for Accreditation (EA) Multilateral Agreement (MLA) and to the International Laboratory Accreditation Cooperation (ILAC) Mutual Recognition Arrangement (MRA) for the recognition of test reports.

The test and/or measurement results, the uncertainties (if applicable) with confidence probability and test methods are given on the following pages which are part of this report.

Seal BIAS TALIBRAS NOT

**Date** 30.05.2023

Person in charge of test

Batuhan AĞA

Approval / Date

Şükrü ÖZEN

This report shall not be reproduced other than in full except with the permission of the BIAS. Testing reports without signature are not valid.



AB-1478-T

AR23-0085-1

05-23

### 1. SAMPLE FEATURES

**1.1.1. Model / Type** : DKM-185 LRM with Relay, DKM-185 LRM without Relay

1.1.2. Trade Name : Datakom

1.1.3. Class : -

1.1.4. Categories : -

**1.1.5. Sample Dimensions** : 100.2x53.2x37.1mm

1.1.6. Serial Number :

Test results only belong to the sample that specified in that sheet.



AB-1478-T

AR23-0085-1

05-23

#### 2. TEST SPECIFICATIONS

2.1. **Test Name**  : Vibration test

2.2. **Test Time**  : Each axis 3.5 hr / Total 10.5 hr

2.3. **Testing Standard**  : \*TS EN 60068-2-6

2.4. **Test Performed**  : Vibration test

2.5. Information Report AR23-0085-0 is invalid. Report AR23-0085-1 is a revised

version of report AR23-0085-0.

2.6. **Ambient Conditions**  : 17±5°C and 35±6 %rh

2.7. Measurement Uncertainty : -

2.8. **Decision Rule** 

Disclaimer

: Decision rule not applied.

BIAS is not responsible for the accuracy of the information

provided by the customer in this report and their impact on the validity of the results. The sample is provided by the customer

and the results apply to the case when the sample is collected.

2.10. Attendees

2.9.

#### 3. TEST INSTRUMENTATION

Equipment Name	Brand/Model	Type/Serial Number	Calibration Validity Date
ELECTRODYNAMIC SHAKER	DONGLING / GT 600 / ES-10-240	D2107303	N/A
CONTROLLER	VR - VIBRATION RESEARCH / VR9500	951C4286	19.01.2024
ACCELEROMETER	DYTRAN / 3055D7	31381	23.08.2023
TEMPERATURE AND HUMIDITY DATALOGGER	TFA / LOG210	21022050111	28.11.2023

This report shall not be reproduced other than in full except with the permission of the BİAS. Testing reports without signature are not



AB-1478-T

AR23-0085-1

05-23

### 4. TESTS

### 4.1. VIBRATION TEST

#### 4.1.1. TEST PROCEDURE

The test performed according to TS EN 60068-2-6 standard.

- The sample is connected to the electrodynamic shaker together with the fixture.
- The test is applied at frequencies between 10 Hz and 150 Hz.
- A constant amplitude of ±0.15 mm is applied in the range of 10 Hz to 58 Hz.
- 2g constant acceleration is applied in the range of 58 Hz to 150 Hz.
- The sample is vibrated for 3.5 hours per axis.
- The test is applied in all 3 axes.
- After the test, the samples are checked by the company.

### 4.1.2. TEST SETUP



FIGURE 4.1.2.1: X Axis Test Setup

This report shall not be reproduced other than in full except with the permission of the BİAS. Testing reports without signature are not valid.



AB-1478-T

AR23-0085-1

05-23



FIGURE 4.1.2.2: Y Axis Test Setup



FIGURE 4.1.2.3 : Z Axis Test Setup

This report shall not be reproduced other than in full except with the permission of the BİAS. Testing reports without signature are not valid.


Tests marked with  $\mbox{\scriptsize *}$  are within the scope of accreditation.




AB-1478-T AR23-0085-1

05-23

## 4.1.3. TEST DATA





This report shall not be reproduced other than in full except with the permission of the BİAS. Testing reports without signature are not valid.



AB-1478-T

AR23-0085-1

05-23





FIGURE 4.1.3.3 : Z Axis Vibration Test Profile

## 5. PHOTOS



PICTURE 5.1 : Before X Axis Vibration Test



PICTURE 5.2: After X Axis Vibration Test

This report shall not be reproduced other than in full except with the permission of the BİAS. Testing reports without signature are not valid.




AB-1478-T

AR23-0085-1

05-23



PICTURE 5.3 : Before Y Axis Vibration Test



PICTURE 5.4: After Y Axis Vibration Test



PICTURE 5.5 : Before Z Axis Vibration Test



PICTURE 5.6 : After Z Axis Vibration Test

This report shall not be reproduced other than in full except with the permission of the BİAS. Testing reports without signature are not valid.

Tests marked with  $\boldsymbol{*}$  are within the scope of accreditation.



AB-1478-T

AR23-0085-1

05-23

## 6. RESULT

The vibration test was performed according to TS EN 60068-2-6 standard. Visually checks were performed after each axis. At the end of the test, no fracture, crack or deformation in the sample was seen.

This report shall not be reproduced other than in full except with the permission of the BİAS. Testing reports without signature are not valid.